

## Step 1

Remove poles from bag and check against component list



## Step 2

Insert pole **B** into pole **A**,  
pole **C** into pole **B** and  
pole **D** into pole **C**



## Step 3

Thread flag onto pole and pull taut ensuring that the pole is fully inserted into the strengthened end of the sleeve take care not to damage the sleeve while threading the flag onto the pole. Do not over bend the pole this could result in damage. Take the bungee and thread through the eyelet on the base of the flag. Creating a loop, thread the metal clip through the loop and pull tight. Attach to the retaining clip on the base of the pole and adjust if necessary



## Step 4

Place pole onto revolving spigot



## Step 4

Place pole onto revolving spigot



## Step 4

Place pole onto revolving spigot



## Step 4

Place pole onto revolving spigot



**Please note:** Maximum wind speed 25mph